

Belts burn on choppers machine with new BTS

User Publication level: Dealer

Quest number

14124

Publication date:

07.11.2013

Updated Date:

10.12.2021

Affected Machines

Bromex CX, Bromex M, Bromex PF, Bromex PM, Bromex PX, Bromex PXD ...

Sometimes when the machine works in the field belts break.

Please check the correct setting

- The correct vertical alignment of V-grooved pulleys (maximum difference 1 mm)
- The belts have been properly tensioned using the adjustment screw (2 pins must be in contact)

