

**MA000726115 Comer Disc clutch D-44 type Calibration mode**

**Quest number:** 14242  
**Publication date:** 12.11.2013

**Affected Machines**  
NG-M 101, TT 15,

Attached the service manual to increase the torque on disc clutch.

In some case, tractor rotation speed at 540 rpm, the torque limiter value at 1500 Nm is too low and disc clutch di is not suitable. Is better to use automatic clutch.



## Media

|                              |                 |
|------------------------------|-----------------|
| Search: <input type="text"/> | Show 10 entries |
| Title                        | Part number     |
| No matching records found    |                 |

Showing 0 to 0 of 0 entries (filtered from 1 total entries)

Showing 1 to 1 of 1 entries

Previous Next